## **CENTER 31** HYGRO THERMOMETER CENTER 31 HYGROTHERMOMETE MAX MIN CENTER 31 HYGROTHERMOMETER Features: • Large, easy-to-read dual LCD displays Humidity and Temperature. • 3%RH humidity accuracy. Calibration available on site. Desk or wall mount. MAX/MIN value monitor.

CE



 Audible and visual alarms, with adjustable set points,

warns if limits are exceeded.



# CENTER 31 HYGRO THERMOMETER

(With ALARM)

### CE

#### **FEATURES**

- Large, easy-to-read dual LCD displays **Humidity and Temperature.**
- 3%RH humidity accuracy.
- Calibration available on site.
- Desk or wall mount.
- MAX/MIN value monitor.
- Audible and visual alarms, with adjustable set points, warns if limits are exceeded.

#### SPECIFICATIONS

#### Measurement Range:

Humidity: 0%RH~100%RH

Temperature: -20°C~60°C; -4°F~140°F

Dew Point Temperature: -20°C~60°C: -4°F~140°F

**Resolution:** 0.1°C/0.1°F/0.1%RH

Accuracy:

Temperature: ±0.8°C, 1.5°F


Humidity: ±3.0%RH Display: LCD, 2lines.

Measuring Interval: 20 sec.

Battery Type: 1.5V AAA size battery x 4 Battery Lifetime: Approx. one year

Operating Condition: 0°C to 40°C; 32°F~104°F **Dimensions:**  $140(L) \times 105(W) \times 26(H) \text{mm} / 265g$ Accessories: Batteries. Instruction Manual













Back stand with hanging support.



33%RH / 75%RH **Humidity Standard (OPTIONAL)** 



<sup>\*</sup> The specifications and other information in this catalogue are subject to change without prior notice